




10 min




x1



x1



A x1




B x2




C x2







1





2



Las patas deben alinearse con la base en la posición correcta, de lo contrario dañará la rosca del tornillo.

Legs must be aligned with the base in the right position, otherwise you will damage the screw thread.

Les pieds doivent être alignés avec la base dans la position adéquate, sinon cela endommagera le fil de la vis.



3

